



## Aviation Warning Lights

An aviation hazard assessment of the Moorabool Wind Farm has been conducted and consultation with the relevant aviation regulatory bodies has taken place. The independent aviation hazard assessment has determined that lighting of turbines is not required.

In accordance with the Moorabool Wind Farm Planning Permit, this determination may be revised should a change in circumstance arise where aviation obstacle lights are required either as a result of a Civil Aviation Safety Authority (CASA) requirement, or as a result of an independent risk assessment demonstrating that operation of the wind farm without obstacle lighting creates an unacceptable public risk.

Therefore, as a precautionary measure, aviation lights will be installed on 41 of the 107 of the wind turbines.

The activation of aviation hazard lights is not proposed for Moorabool Wind Farm at this time.



T: 1800 019 660  
E: [info@mooraboolwindfarm.com](mailto:info@mooraboolwindfarm.com)  
W: [www.mooraboolwindfarm.com](http://www.mooraboolwindfarm.com)