

**Media Statement 26 November 2025**

Moorabool Wind Farm is aware that the presence of asbestos has been identified in spare brake pads used on some of the internal service lifting devices, which are located inside our wind turbines.

Since being advised of this issue, our focus has been on the health and safety of our staff, contractors and the community; and ensuring that all relevant authorities are informed and investigations and robust testing undertaken.

Turbine interior atmospheric testing results to date have returned negative results. The brake pad location within the turbines is enclosed, and the lifting devices are in an area not accessible to the public. The risk level has been assessed by independent specialists to be very low.

We will continue to stay in constant communication with Goldwind to ensure they have the access and support they need to undertake a thorough investigation and assessment.

The health and safety of our staff, contractors and wider community remain our ultimate focus and priority.

We will provide updates to the community as more information comes to hand and make any necessary changes to our operations as required.

For further information please contact [info@mooraboolwindfarm.com](mailto:info@mooraboolwindfarm.com)