

Repairs and Road Resurfacing at Moorabool South Wind Farm

Mount Wallace Ballark Road and Bungeeltap South Road will be resurfaced between late-September and late November 2021. This will involve road closures, diversions and speed reductions along sections of the roads for a period of time.

Bungeeltap South Road - Resurfacing

Diversions will be in place from mid-September until late October.

Road users will be diverted via Ballan Meredith Road and Mount Wallace Ballark Road.

Mount Wallace Ballark Road – Resurfacing

Diversions will be in place from early-October until mid to late November.

Road users will be diverted via Ballan Meredith Road and Bungeeltap South Road.

Contact Us:

1800 019 660,
info@mooraboolwindfarm.com

Moorabool wind farm apologises for any inconvenience caused during the works.

